

ECONOMIC HARDSHIP REPORT

CONTENTS OF BINDER

Tab	Bruce Baird Letter
Tab	Economic Hardship Application
Tab	Economic Hardship Report
EXHIBITS TO ECONOMIC HARDSHIP REPORT	
A	Bishop Place Settlement Statements
B	Engineering Letter from Jeff Ambrose, S.E., P.E.
C	Engineering Letter from Robert C. Conder, S.E., P.E.
D	Loan Documents from Redevelopment Agency
E	2012-2016 Property Taxes (2017 in Appeal- See Ex S)
F	Bishop Place Appraisals – Pages two--eight of each property (complete appraisal for each individual property on flash drive)
G	Realtor Letter – John Maxim
H	Architect Letter-Edward Probyn James III, Architect, AICP
I	Owner Letter-Donald E. Armstrong, President of International Real Estate Solutions, Inc.
J	Bishop Place photos from 1936 to 2003 (on flash drive)
K	Bishop Place photos from 2012 (on flash drive)
L	Bishop Place photos from January 2013 (on flash drive)
M	Bishop Place photos from February 2013 (on flash drive)
N	Bishop Place photos from July 2013 (on flash drive)
O	Bishop Place photos from February 2016 (on flash drive)
P	Bishop Place photos from Application to Demolish (on flash drive)
Q	Bishop Place photos from September 2017 (on flash drive)
R	Bishop Place Tax Appeals
S	Contractor Letter – Breen Construction
T	Estimated Construction Costs for "Rental" Value
U	Estimated Construction Costs for "For Sale" Value
V	IRES Panel Representative Curriculum Vitae
W	Bishop Place Individual Property Analysis
X	Appraisal of All Bishop Place Properties combined

Note: All the exhibits are included on the flash drive provided.

See petition PLNHLC2017-00030 (432 N. 300 West) for combined electronic files related to all Bishop Place Economic Hardship Applications. Individual property tax files, appraisals, and specific property photos located under each property address.